

- **Latest Govt Job updates**
- Private Job updates
- Free Mock tests available

Visit - teachingninja.in

# **RPSC**

Previous Year Paper ME Lecturer 2011



श्रेन्यमेतकार ००० इत्य ०० ४४०० छ। १: विषयः//Subject

Salance Salanceine

कांड / (Gode : - (1) 2

गुरितको में गुरुत की संख्या 🖰 🦠

Miniser of Pages in Booklets 16

स्प्रीत्तका प्राप्यको क्षेत्रसंख्या Number of Caestions in Bookles - 100

समय / Ime 2 च र मिलार

leath Technedus. Schoolfeateal

Mechanical Engineering

)2 [A

min / M

-पूर्णिक / Maximum Marks : 1008

#### INSTRUCTIONS

- I. Answer all questions.
- 2. All questions carry equal marks.
- 3. Only one answer is to be given for each question.
- If more than one answers are marked, it would be treated as wrong answer.
- Each question has four alternative responses marked serially as 1, 2, 3, 4. You have to darken only one circle or bubble indicating the correct answer on the Answer Sheet using BLUE BALL POINT PEN.
- 6. 1/3 part of the mark(s) of each question will be deducted for each wrong answer. (A wrong answer means an incorrect answer or more than one answers for any question. Leaving all the relevant circles or bubbles of any question blank will not be considered as wrong answer.)
- 7. The candidate should ensure that Series Code of the Question Paper Booklet and Answer Sheet must be same after opening the envelopes. In case they are different, a candidate must obtain another Question Paper of the same series. Candidate himself shall be responsible for ensuring this.
- Mobile Phone or any other electronic gadget in the examination hall is strictly prohibited. A candidate found with any of such objectionable material with him/her will be strictly dealt as per rules.
- Please correctly fill your Roll Number in O.M.R. Sheet. 5 marks will be deducted for filling wrong or incomplete Roll Number.

Warning: If a candidate is found copying or if any unauthorised material is found in his/her possession, F.I.R. would be lodged against him/her in the Police Station and he/she would liable to be prosecuted under Section 3 of the R.P.E. (Prevention of Unfairmeans) Act, 1992. Commission may also debar him/her permanently from all future examinations of the Commission.

#### निर्देश

- 1. सभी प्रश्नों के उत्तर दीजिए।
- 2. सभी प्रश्नों के अंक समान हैं।
- 3. प्रत्येक प्रश्न का केवल एक ही उत्तर दीजिए।
- 4. एक से अधिक उत्तर देने की दशा में प्रश्न के उत्तर को गलत माना जाएगा।
- 5. प्रत्येक प्रश्न के चार वैकल्पिक उत्तर दिये गये हैं, जिन्हें क्रमशः 1, 2, 3, 4 अंकित किया गया हैं। अभ्यर्थी को सही उत्तर निर्दिष्ट करते हुए उनमें से केवल एक गोले अथवा बबल को उत्तर-पत्रक पर नीले बॉल प्वाइंट पेन से गहरा करना है ।
- 5. प्रत्येक गलत उत्तर के लिए प्रश्न अंक का 1/3 भाग काटा जायेगा। गलत उत्तर से तात्पर्य अशुद्ध उत्तर अथवां किसी भी प्रश्न के एक से अधिक उत्तर से है । किसी भी प्रश्न से संबंधित गोले या बबल को खाली छोड़ना गलत उत्तर नहीं माना जायेगा।
- 7. प्रश्न-पञ्च पुस्तिका एवं उत्तर पञक के लिफाफ की सील खोलने पर परीक्षार्थी यह सुनिश्चित कर लें कि उसके प्रश्न-पञ्च पुस्तिका पर वहीं सीरीज अंकित है जो उत्तर पञक पर अंकित है। इसमें कोई भिन्नता हो तो वीक्षक से प्रश्न-पञ्च की ही सीरीज वाला दूसरा प्रश्न-पञ्च का लिफाफा प्राप्त कर लें। ऐसा न करने पर जिम्मेदारी अध्यर्थी की होगी।
- 8. मोबाईल फोन अथवा इलेक्ट्रोनिक यंत्र का परीक्षा हॉल में प्रयोग पूर्णतया वर्जित हैं। यदि किसी अभ्यर्थी के पास ऐसी कोई वर्जित सामग्री मिलती है तो उसके विरुद्ध आयोग द्वारा नियमानुसार कार्यवाही की जायेगी।
- कृपया अपना रोल नम्बर ओ.एम.आर. पत्रक पर सावधानी पूर्वक सही भरें। गलत अथवा अपूर्ण रोल नम्बर भरने पर 5 अंक कुल प्राप्तांकों में से अनिवार्य रूप से काटे जाएंगे।

चेतावनी: अगर कोई अम्यर्थी नकल करते पकड़ा जाता है या उसके पास से कोई अनधिकृत सामग्री पाई जाती है, तो उस अम्यर्थी के विरुद्ध पुलिस में प्राथमिकी दर्ज कराई जायेगी और आर. पी. ई. (अनुचित साधनों की रोकथाम) अधिनियम, 1992 के नियम 3 के तहत कार्यवाही की जायेगी। साथ ही आयोग ऐसे अम्यर्थी को मविष्य में होने वाली आयोग की समस्त परीक्षाओं से विवर्जित कर सकता है।

02/BME5\_A]

[Contd...





The crank case of many diesel engines are kept under a slight vacuum to

- (1) Improve fuel economy
- (2) Improve air charge velocity
- (3) Reduce the risk of crank case explosion
- (4) All of the above
- 2 Engine operating conditions may be indicated by the colour of exhaust smoke. Black smoke could indicate
  - (1) Insufficient speed droop setting
  - (2) Overloaded engine
  - (3) Clogged drain holes in the oil control rings
  - (4) Complete combustion
- In a normally operating diesel engine the main source of lubricating oil contamination in the crank case is a result of the
  - (1) Metal particles loosened by wear
  - (2) Condensation of water vapours
  - (3) Break down of the lubricating oil itself
  - (4) Fuel dilution
- 4 The bore and stroke of the cylinder of a six cylinder engine working on an Otto cycle are 17cm and 30 cm respectively, total clearance volume is 9225 cm<sup>3</sup>, and then what is the compression ratio?
  - (1) 7.8

(2) 6.2

(3) 15.8

(4) 5.4

- 5 . Which of the following symptoms shows that the combustion is necessarily complete?
  - (1) Presence of free carbon in exhaust
    - (2) Presence of CO in exhaust
  - (3) Presence of Oxygen in exhaust
  - (4) Presence of Nitrogen in exhaust
- 6 What is the purpose of supercharging an engine?
  - (1) To increase the power output
  - (2) To reduce specific fuel consumption
  - (3) To reduce the noise of the engine
  - (4) To improve cooling of cylinders

### 7 Consider the following:

- 1. Catalytic convertor
- 2. Use of high compression ratio
- 3. Oxidation catalyst in the exhaust manifold
- 4. Use of high degree of supercharger

By which of these techniques, can the oxides of nitrogen in the exhaust be controlled?

(1) 1 only

- (2) 2 and 4 only
- (3) 2, 3 and 4 only
- (4) 1, 2, 3 and 4

Which phenomenon has the most adverse effect on volumetric efficiency when engine works at high speeds?

- (1) Flow friction and choking
- (2) Ram effect and chocking
- (3) Flow friction and charge heating
- (4) Charge heating and back flow

### 9 Consider the following:

- 1. Increased cetane number
- 2. Increased compression ratio
- 3. Increased injection advance
- 4. Increased air turbulence

Which of the factors will reduce the physical delay in diesel engine?

- (1) 1, 2 and 3 only
- (2) 2 and 4 only
- (3) 2, 3 and 4 only
- (4) 1, 2, 3 and 4

## 10 Consider the following factors:

Diesel engine knock can be reduced by increasing

l. Engine speed

- 2. Compression ratio
- 3. Degree of supercharge
- 4. Injection advance

Which of the statements is/are true?

- (l) 1, 2 and 3 only
- (2) 2 and 3 only
- (3) 1, 3 and 4 only
- (4) 2 only

02/BME5\_A]

Contd...

V.		
11 When does ignition initiates in a Spark Ignition Engine?		
	(1) Immediately after spark	
	(2) Immediately after completion of physical and chemical delay	
	(3) Immediately after the completion of Ignition lag	
	(4) just after completion of flame propagation:	
12	If the evaporator temperature of a plant is lowered keeping the condenser	
	temp. constant, the power input of compressor required will be	
•	(1) same (2) more	
	(3) less (4) unpredictable	
13	Where does the lowest temp occur in a vapor compression cycle?	
	(1) condenser (2) evaporator	
	(3) compressor (4) drier	
14		
**	(1) the SI unit used in refrigeration problem	
	(2) the cooling effect produced by melting 1 ton of ice	
	(3) the refrigeration effect to freeze 1 ton of water at 0°C into ice at 0°C in 24 hrs.	
	(4) the refrigeration effect to produce 1 ton of ice at NTP condition	
15	Which of the following refrigerant has the highest critical point pressure?	
	(1) Freon-11 (2) Freon-12	
	(3) Freon-22 (4) Ammonia	
16	A hermetically sealed unit implies	
10	(1) Compressor motor is sealed	
	(2) Compressor is sealed	
	(3) Refrigerant cycle is sealed	
	(4) Compressor and motor are sealed	
17	An evaporator pressure regulator performs the following function	
	(1) Monitors evaporator temp	
	(2) Maintains compressor inlet pressure	
1	(3) Keeps pressure up for system needs	
	(4) All of these	
18	The conditioned air supplied to the room must have the capacity	
10	to take up	
	(1) Room sensible heat load only	
•	(2) Room latent heat only	
	(3) Both room sensible heat and latent heat loads	
	(4) None of the above	
	City a rione of the goods	

ď	L
v	•

02

			oling process					
	(1) increases	(2)	decreases					
	(3) remains same	(4)	unpredictable					
20	Piston rings are made of							
i C	(1) cast iron	(2)	brass					
٠.	(3) aluminium	juc. <b>(4)</b>	spring steel					
21	The addition of iron oxide to	the foundr	y sand improves th					
	(1) Bonding	(2)	Green strength					
	(3) Hot strength	(4)	Permeability					
22	Surface finish of casting depe	Surface finish of casting depends upon						
	(1) Mould dressing	(2)	Pattern finish					
	(3) Sand compactness	(4)	All of the above					
23	Core prints are used for							
	(1) Strengthen core							
	(2) Form seat to support an	d hold the	core in place					
	(3) Fabricate core		•					
	(4) None of the above							
24	In drawing operation the metal flows due to							
24	In drawing operation the meta	al flows due	to					
24		al flows due (2)	to Work hardening					
24								
24	(1) Ductility (3) Plasticity	(2) (4)	Work hardening Shearing					
٠.	<ul><li>(i) Ductility</li><li>(3) Plasticity</li><li>Mass production on metallic of</li></ul>	(2) (4) cans are usi	Work hardening Shearing ually done by					
	<ul><li>(1) Ductility</li><li>(3) Plasticity</li><li>Mass production on metallic (1) embossing</li></ul>	(2) (4) cans are usi (2)	Work hardening Shearing Hally done by coining					
٠.	<ul><li>(i) Ductility</li><li>(3) Plasticity</li><li>Mass production on metallic of</li></ul>	(2) (4) cans are usi (2)	Work hardening Shearing ually done by					
25	<ul><li>(1) Ductility</li><li>(3) Plasticity</li><li>Mass production on metallic (1) embossing</li></ul>	(2) (4) cans are usi (2) (4)	Work hardening Shearing hally done by coining drawing					
25	<ul> <li>(1) Ductility</li> <li>(3) Plasticity</li> <li>Mass production on metallic (1) embossing</li> <li>(3) spinning</li> </ul>	(2) (4) cans are usi (2) (4)	Work hardening Shearing hally done by coining drawing					
25	<ol> <li>Ductility</li> <li>Plasticity</li> <li>Mass production on metallic (1) embossing</li> <li>spinning</li> </ol> An important product manufacture	(2) (4) cans are usi (2) (4) ctured by re (2)	Work hardening Shearing Hally done by coining drawing blling is					
25	<ul> <li>(i) Ductility</li> <li>(3) Plasticity</li> <li>Mass production on metallic (1) embossing</li> <li>(3) spinning</li> <li>An important product manufact</li> <li>(1) I-section</li> <li>(3) Metal Rolls</li> </ul>	(2) (4) cans are usi (2) (4) ctured by ro (2) (4)	Work hardening Shearing  ally done by coining drawing  blling is Tubes Rollers					
25	<ul> <li>(i) Ductility</li> <li>(3) Plasticity</li> <li>Mass production on metallic (1) embossing</li> <li>(3) spinning</li> <li>An important product manufact</li> <li>(1) I-section</li> <li>(3) Metal Rolls</li> </ul>	(2) (4) cans are usi (2) (4) ctured by re (2) (4) ed in Jigs a	Work hardening Shearing  ally done by coining drawing  blling is Tubes Rollers  and Fixture because					
24 25 26 27	(1) Ductility (3) Plasticity  Mass production on metallic (1) embossing (3) spinning  An important product manufact (1) I-section (3) Metal Rolls  A diamond locating pin is use	(2) (4) cans are usi (2) (4) ctured by re (2) (4) ed in Jigs and wear resi	Work hardening Shearing  ally done by coining drawing  blling is Tubes Rollers  and Fixture because					
25	(1) Ductility (3) Plasticity  Mass production on metallic (1) embossing (3) spinning  An important product manufact (1) I-section (3) Metal Rolls  A diamond locating pin is use (1) Diamond is very hard an	(2) (4) cans are usi (2) (4) ctured by re (2) (4) ed in Jigs and wear residuce	Work hardening Shearing  ually done by coining drawing  blling is Tubes Rollers  and Fixture because istant					

o'	L
v	



			•
28	Bench vice is an example of		
	(1) Jig	(2)	Fixture
:	(3) Locator	(4)	Clamping device
29	Surging basically implies		
	(1) Unsteady periodic and rever	sed flov	v
	(2) Forward motion of axial sp		
			of air produced in compressor
	(4) Forward movement of aircr		
30	A centrifugal pump is started wi	th the d	elivery valve kent
	(1) fully open	(2)	· ·
	(3) partially open		50% open
	Cy Paramy Spor		от орган
31	and the second		
	(1) excessive leakage of flowin	_	
•	(2) bursting of pipe under high		
	(3) sudden stoppage of flow by		sure of a valve
	(4) hitting of pipe with hamme	r	
32	Unit of Kinematic viscosity is		
جِن	(1) m/sec <sup>2</sup>	(2)	m²/sec
	(3) m/sec	(4)	m <sup>2</sup> /sec <sup>3</sup>
		. (-)	
33	Hydrodynamic and thermal bour	dary lay	er thickness is equal when
	Prandtl number		
	(1) =0	(2)	<1
	(3) =1	(4)	>1
34	In a steam power plant the ratio of		
٠.	to the amount of heat supplied pe		· · · · · · · · · · · · · · · · · · ·
	(1) Stage efficiency		Degree of reaction
	(3) Rankine efficiency	(4)	Relative efficiency
35	If heat and mass transfer take place	simultane	cously, the ratio of heat transfer
/	coefficient to the mass transfer co	efficient	is a function of the ratio of
	(1) Schmidt and Reynolds num	ber	
	(2) Schmidt and Prandtl numbe		
	(3) Nusselt and Lewis numbers		*. <b>'</b>
	(4) Reynolds and Lewis number		
36	Which one of the following	nution !-	mana annieles
JU -	Which one of the following proper strain rate?	ernes is	more sensitive to increase in
	(1) Yield strength	(2)	Proportional Limit
	(3) Elastic Limit	(2)	Tensile Strength
•		(7)	zonono puonem
0.1			

	stiffness 10N/mm and 5N/mm. The equivalent spring stiffness of the two springs is nearly
	(1) 0.3N/mm (3) 5N/mm (2) 3.3N/mm (4) 15N/mm
38	Critical speed of the shaft is affected by  (1) diameter and eccentricity of the shaft  (2) span and eccentricity of the shaft  (3) diameter and span of the shaft  (4) span of the shaft
39	Which one of the following tolerances set on inner diameter and outer diameter respectively of headed jig bush for press for correct fit?  (1) G7h6  (2) F7n6  (3) H7h6  (4) F7j6
40	Clausius- Clapeyron equation gives the slope of a curve in
	(1) p-v diagram (3) p-T diagram (4) T-S diagram
41	Stability of freely falling object is assured if its centre of  (1) Buoyancy lies below its centre of gravity  (2) Gravity coincides with its centre of gravity  (3) Gravity lies below its meta centre  (4) Buoyancy lies below its meta centre
42	The maximum shear stress occurs on the outer most fibers of a circular shaft under torsion. In a close coiled helical spring the maximum shear stress occurs on the

In a single reduction, a large velocity ratio is required. The best transmission is

Spur gear drive

Helical gear drive (2)

Bevel gear drive

**(4)** Worm gear drive

Concepts in "Total Quality Management (TQM)" are attributed to

George Dantzig

(2) Taiichi Ohno .

(3) W. Edwards Deming

(4) Henry Ford

 $02_{\text{/BME5\_A]}}$ 



45	To	compete	on	speed,	a	company	must
----	----	---------	----	--------	---	---------	------

- (1) produce a single product
- (2) centralize all operations
- (3) use only one supplier
- (4) have quick feedback mechanisms
- 46 A product has MTBF of 200 hours and a MTTR of 10 hours. What is its system availability?
  - (1) .048

(2) .050

(3) .952

(4) 1.050

- Which of the following characteristics is *not usually* associated with batch production?
  - (1) products made to customer order
  - (2) low volume
  - (3) stable, predictable demand
  - (4) general purpose equipment
- What is the break-even point for the following situations: Fixed cost of product Rs 2000; variable cost of product Rs 5; price per unit Rs 10?
  - (1) 4 units

(2) 40 units

(3) 400 units

(4) 1000 units

- 49 A relationship diagram is
  - (1) a format for displaying manager's preferences for department locations
  - (2) a schematic diagram that uses weighted lines to denote location preference
  - (3). a type of schematic layout diagram that includes space requirements
  - (4) a network that describes restrictions on the order in which work elements must be performed
- 50 Which of the following statements concerning a Gantt chart is true?
  - Gantt charts are particularly helpful for scheduling and planning large projects.
  - (2) Gantt charts are particularly helpful for scheduling and planning projects with complex precedence relationships.
  - (3) The Gantt chart has been a popular project scheduling tool, but is not widely used now.
  - (4) The Gantt chart indicates where extra time is available and activities can be delayed.



- رگ م
- With the PERT approach, the variance of the total project completion time is calculated by
  - (1) adding all the individual activity variances together
  - (2) adding all the individual activity variances not on the critical path
  - (3) adding all the individual activity variances on the critical path
  - (4) choosing the largest variance that occurs from the pool of individual activity variances
- 52 Which of the following is true concerning the weighted moving average?
  - (1) The oldest data will generally be given the greatest weight.
  - (2) If the weighted moving average forecast is 57.3, then the final forecast must be rounded up to 58.
  - (3) If the most recent periods are too heavily weighted, the forecast might overreact.
  - (4) The weighted moving average is usually more accurate than a simple moving average.
- 53 For a company that uses a periodic inventory system, which of the following is true?
  - (1) inventory is counted only at specific time intervals
  - (2) the order is for a fixed quantity which minimizes inventory costs
  - (3) the inventory system is also referred to as a perpetual inventory system
  - (4) the company is using a fixed-order-quantity system
- 54 Which of the following statements concerning the basic EOQ model is true?
  - (1) A decrease in demand will increase the EOQ value.
  - (2) If an actual order quantity is smaller than the EOQ, the annual holding cost is less than the annual ordering cost.
  - (3) An increase in holding cost will increase the EOQ value.
  - (4) In the EOQ formula there is an inverse relationship between setup and carrying costs.
- For a company with an average daily demand of 9 units and a standard deviation of 3 units, a 9-day lead time, and a 95% service level, which of the following statements is true?
  - (1) The reorder point is about 81 units
  - (2) The safety stock is about 15 units
  - (3) The reorder point is about 96 days
  - (4) The reorder point is about 81 days





Which of the following is not a pasic element of the JIT production system?

- (1) cellular layous
- (2) push production system
- (3) small-lot production
- (4) flexible resources

57 Maintenance that involves a system of periodic inspection and maintenance designed to keep a machine in operation is called

- (1) preventive maintenance
- (2) total productive maintenance
- (3) predictive maintenance
- (4) breakdown maintenance

58 Which of the following heuristics in a one-machine shop will always minimize flow time and average number of jobs in the system?

- (1) SPT
- (2) DDATE
- (3) CR
- (4) FCFS

59 All of the following are considered nonproductive activities relating to equipment except

- (1) setting up or breaking down a machine
- (2) maintaining the machine
- (3) waiting for workers or material
- (4) all of the above are nonproductive activities

60 Whose book, entitled Quality is Free, emphasized the cost of quality?

- (1) Walter Shewhart
- (2) Phillip Crosby
- (3) W. Edwards Deming
- (4) Joseph Juran

- 61 Which of the following is not true concerning the ISO 9000 ?
  - (I) The ISO 9000 committee establishes generic quality standards for manufacturing firms worldwide.
  - (2) The ISO 9000 committee is a government organization that is a subset of the United Nations.
  - (3) The ISO 9000 is a guide for using the other four standards in the series 9001 through 9004.
  - (4) The ISO 9000 does not tell management how to meet requirements but does indicate what is required.
- A p-chart has been prepared. Computations show that the average proportion defective is .032, while the standard deviation is .0176. From this data, what are the 3-sigma control limits for this chart?
  - (1) LCL=.032 UCL=.085
  - (2) LCL=.053 UCL=.032
  - (3) LCL = 0 UCL = .085
  - (4) not enough information to determine the control limits
- A part has a length specification of 2 mm with tolerances of  $\pm$  .03 mm. The current process has an average length of 2.01 mm with a standard deviation of .02 mm. What is the value of the  $C_{\perp}$  ratio?
  - (1) .167
  - (2) .333
  - (3) .500
  - (4) 1.333
- 64 For a facility with an average arrival rate of 45 units per hour and a service rate of 60 units per hour, with a maximum system size of 3 units, which of the following statements is true?
  - (1) The probability the system is full is .63
  - (2) The average number of units waiting to be served and being served is 1.15 units
  - (3) The average time a unit spends waiting to be served is 1.8 minutes
  - (4) The average number of units waiting to be served is .64 units
- A company wishes to determine the proportion of time workers are idle. Using work sampling, the idle time during 150 observations is 26%. If the company wants a 95% confidence interval, how many more observations are needed if the company wants to be within +/-4% of the true proportion?
  - (1) 9 observations

- (2) 150 observations
- (3) 312 observations
- (4) 462 observations





66	(1) average expected payoff	ine of pe	errect information is the
	(2) value of a decision given	perfect in	nformation
	(3) value of a decision without	it perfect	information
	(4) maximum value a decision perfect information	maker is	s willing to pay to purchase
67	Which of the following criteria we equipment and components likely analysis?	y consider	
	<ol> <li>land and construction costs</li> <li>availability of skilled work</li> </ol>		
	(3) transportation costs		
	(4) proximity to raw materials		. 0.
68	Which of the following location of evaluating different locations be the distance?	_	
	(1) load-distance technique	(2)	location factor rating
	(3) center-of-gravity technique	A	· · · · · · · · · · · · · · · · · · ·
<b>6</b> 9	A linear programming model is	-	
	(1) probabilistic model	(2)	·
	(3) graphic model	· (4)	physical model
70	The term which reflects an accepthe consumer is?	otable pro	portion of defects in a lot to
	(I) AOQ	(2)	LTPD
	(3) OC	(4)	AQL
71	While machining which of the	following	improves surface finish ?
	(1) Increased depth of cut (2) Increased feed rate	•	•
	(3) Increased cutting speed		
	(4) Formation of built-up edge		
	(.) Tomation of built-up eago		
72	At what rpm should a lathe be min when turning a rod of dian	run to gineter 40	ve a cutting speed of 20 m/mm?
	(1) 100 rpm	(2)	160 rpm
	(3) 200 rpm	(4)	250 rpm
73	Petrol engine carburetors are ma	nufacture	d by
	(1) Sand casting	(2)	Centrifugal casting
	(3) Shell casting	(4)	Die casting
02	/BME5_A] 12	2	[Contd

2		
74	Which of the following cast iron	is resistant to attack by sea water?
	(1) Low chromium cast iron	(2) Low nickel cast iron
	(3) Low sulphur cast iron	(4) Low phosphorous cast iron
75	The coolant generally used while	machining with carbide tools is
	(1) Kerosene	(2) Water
٠	(3) Soluble oil	(4) Graphite
76	Among the following, which mater	rial is having highest machine-ability?
	(1) Cast iron	(2) Mild steel
	(3) High carbon steel	(4) Aluminium
77	Which of the following qualifies	as a precision casting process ?
	(1) Ingot casting	(2) Investment casting
	(3) Sand casting	(4) Shell molding
78	Which of the following terms bes	st describes cemented carbide?
	(1) Ceramic	(2) Cermet
,	(3) Composite	(4) Metal
79		hich one of the following temperature pint (Tm) of the given metal on an (2) 0.2 Tm
	(3) 0.4 Tm	
	(5) 0.4 1111	(4) 0.6 Tm
80		e in radius of the work part is equal
	to which one of the following?	(2)
	(1) 1 × depth of cut	(2) 2 × depth of cut
	(3) 1 × feed	(4) 2 × feed
81	Which of the following abrasive mat	terials is most appropriate for grinding
	hardened tool steel?	
	(1) Aluminium oxide	(2) Cubic boron nitride
	(3) Diamond	(4) Silicon carbide
82	Of the following processes, which removal rates?	one is noted for the highest material
-	(1) Electric discharge machining	•
:	(2) Electrochemical machining	

02/BME5\_A]

Laser beam machining Plasma arc cutting



こし		
83	Which of the following are advan	ntages of die casting over sand casting?
	(1) Higher melting temperature	e metals
	(2) Higher production rates	
	(3) Larger parts can be cast	·
	(4) Mold cannot be reused	
84	<del>-</del> -	esses for the new ceramic materials
	accomplishes shaping and sinter	ring simultaneously?
	(1) Doctor-blade process	(2) Freeze drying
	(3) Hot pressing	(4) Injection molding
. 05	Which of the following charging a	untariale la mant amora de la Caracia dina
85	steel and cast iron?	naterials is most appropriate for grinding
		(2) Cubic boron nitride
	<ul><li>(1) Aluminium oxide</li><li>(3) Diamond</li></ul>	
	(3) Diamond	(4) Silicon carbide
86	Seamless tubes are made by	
	(1) piercing operation	(2) hot forging
	(3) power rolling	(4) none of the above
87	In electro-chemical milling oper	ation, the gap between tool and work
	kept is of the order of	
	(1) No gap	(2) 0.25 mm
Sec.	(3) 0.75 mm	(4) 1.25 mm
88		ark erosion machining process is called
	(1) Arc	(2) Capacitor
	(3) Electrode	(4) Dielectric
89	Gear teeth vernier is used to m	neasure
	(1) Circular pitch	(2) Depth of tooth
	(3) Tooth thickness	(4) Pitch line thickness
90	In blanking operation, the angle	of shear is given on
	(1) Punch	(2) Die
	(3) Both punch and die	(4) None of the above
A	5.11.1.1	

Drilled holes and honed holes could be designated by which of the following grades?

14

(1) H<sub>5</sub>, H<sub>11</sub>

 $H_{6}, H_{10}, H_{5}$ 

(3)  $H_{8}$ ,  $H_{6}$ 

The processes are commonly used for producing powder 92

(1) Atomization

Reduction Process (2)

(3) Electrolytic process

(4) All of the above

 $02_{\text{/BME5\_A]}}$ 

[Contd...

2			
93	What else does hydrogen electricity ?	fuelled fuel cell	produce other than heat and
1 "	(1) Carbon dioxide	(2)	Pure water
• .*	(3) Nitric acid	(4)	Natural gas
94	Centralised collection device	e for generating	power from the Sun is called
	(1) Fuel cell	(2)	Power tower
٠	(3) Solar collector	(4)	Solar photovoltaic
95	The future growth of larg	e scale hydro p mited because	ower plants in the developed
	(1) the release of impou	nded water alte	rs stream flow patterns
	(2) most economical site		
· 1	(3) reservoirs eventually	fill with sedim	ents
	(4) all of the above		
96	The nodal agency for co- under EC act in India is	ordinating the e	energy conservation activities
	(1) Bureau of Indian Sta	andards	
	(2) Bureau of Energy E		e de la companya del companya de la companya del companya de la co
	(3) Bureau of Energy E		
	(4) Bureau of Energy ar		
	(), ====================================	Latvii ommont	<u>:</u>
97	What type of energy is d	erived from hea	ted ground mater 2
	(1) Solar energy	(2)	= •
	(3) Nuclear energy		Geo-thermal energy
	(5) Itacical chergy	(4)	OTEC
98	Important wasta managam		
70	Important waste managem		-
•-///	(1) Disposal-biodegradab		Recycling
	(3) Landfills	(4)	All of the above
00	Am almosti harra 190		
99	1200 W of electric energy	. The total cost	es. During this time it uses of the electricity will be if
	electricity costs 7 paisa po		***
٠.	(1) 252 paisa	(2)	25200 paisa
	(3) 4200 paisa	(4)	4:2 paisa
* ^ ~	3774		
100	What two gases are typical		a fuel cell ?
1.	(1) Hydrogen and nitroge	en (2)	Hydrogen and oxygen

Helium and nitrogen

Oxygen and nitrogen

(4)





## SPACE FOR ROUGH WORK



 $02_{\rm /BME5\_A]}$ 

